


5-3

F.No.IFB(MB)/7-1/NOC-Gov.Sch/166
नरीक्षक अग्निशमन का कार्यालय
OFFICE OF THE INSPECTOR FIRE BRIGADE
मायाबंदर
MAYABUNDER



Dated 17th September, 2021

To

The Principal
G.S.S.S Pahalgaon
Mayabunder

Sub: Shortfall regarding NOC from Fire Dept., reg-

Sir/Madam

It is to inform you that the inspection from the fire point of view In-charge, Fire Station Mayabunder has been already issued a letter vide No. 268 dated 29/03/2018 to DEO, Mayabunder (Copy enclosed in your school EMAIL ID)

Now, a letter has been received from your office vide F.No. 5-10/GSSS/PG/MB/2015/6995 Dated 15/09/2021, for issuing FCC. In response to this the school has been re-inspected and observed that the shortfalls as stated in our above mentioned letter is not fulfilled. Hence, it is once again requested to attend the earlier mentioned shortfalls and also the following guidelines should be followed for Fire Safety Certificate.

- 1) Training of all teaching and non teaching staffs those not acquainted with operation of fire fighting equipments and evacuation drill shall acquire the same from nearby Fire Station.
- 2) Register to be maintained regarding conduct of evacuation/safety drills at least twice in a year i.e. in the starting session and mid session in which the staff of nearby Fire Station will be the "Observer" of the drill.
- 3) A New Fire/Emergency evacuation plan should be affixed in a prominent place to be view by all incumbent in the school. The plan should also show the locations of the fire-fighting equipment. The safe zone should be clearly indicated in the Evacuation/Fire plan.
- 4) Loose wiring should be channeled.
- 5) A Fire/emergency Alarm shall be installed.

- 6) All the classes should have present strength mentioned in the classrooms at all time to be viewed by all the subjects' teachers also.
- 7) It should be ensured that the exit /evacuation routes are not wet so as to avoid slippery nature of the floor.
- 8) All the evacuation/exits routes should be clear from hindrance such as table, benches, etc. should be removed from the path of exit.
- 9) An underground water storage tank of 10,000 ltrs.(approx) is required exclusively for fire-fighting purpose.
- 10) A register shall be maintained for extinguishers installed in the school with details of type of extinguisher, installation place, manufacturing date and consequent inspections by fire brigade staffs.
- 11) Safe zone and safe zone route should be clear.
- 12) Google satellite image (zoomed in and out) of the School is to be provided
- 13) All dangerous trees including fruit bearing trees inside the school premise has to be cut down for safety of the students.
- 14) Till class I, the classes should be in the Ground Floor and class II can be in First Floor. Any class room having 45 students and more should have two exits

After compliance of above said shortfalls, kindly intimate for re-inspection.



(DilipKarmakar)

Inspector Fire Brigade
Mayabunder

Inspector Fire Brigade
निरीक्षक अग्निशमन
Mayabunder
मायाबंदर

Copy to:

- 1) The Reader to SP (Fire).
- 2) The Reader to DySP (Fire).
- 3) The I/C FS Mayabunder for information.
- 4) File concern.